



TECH NOTES

Fender Musical Instruments Corp.
7975 North Hayden Road Scottsdale, Arizona 85258

TECH NOTE # TN 99-4

ISSUE DATE: Dec., 1999

ISSUED BY: J. Benson

PAGE: 1 of 1

PRODUCT(S) AFFECTED:

SUNN 300T

(Units built prior to 12-7-99)

SYMPTOMS:

A failure causes output tubes to lose bias, causing the screen resistors to blow, and causing output tube failure; If there are no outward symptoms, then implementation of this TN may increase reliability of the unit.

CONDITION:

Ratings on R333 & R353 are borderline, and may allow burnout under some operating conditions. Increase value from 1/4W to 1/2W. Note: these parts cannot be evaluated by a visual check, since they may not show outward signs of stress.

PARTS REQUIRED:

2 0039186001 RES CF 1/2W 330k 5%

REQUIRED ACTION:

- 1) Visually inspect R333 & R353 to determine that they are 1/4W parts.
- 2) If so, remove them.
- 3) Replace parts with 1/2W parts.

WARRANTY CLAIM INSTRUCTIONS:

The above modification should be performed on any **SUNN 300T** that is in warranty, whether or not exhibiting the above symptoms. For proper labor reimbursement, please indicate the Tech Note Number TN99-4 in the Authorization Code Box (Box # 12) on the Warranty Reimbursement Form. Labor reimbursement = 3/4 Hour (U.S. only).