

Technical Service Bulletin No. 13

THIS BULLETIN REPLACES BULLETIN NO. 3 AND NO. 7 Pot FP Plus

Created by: Lab.gruppen AB Service Department

Date: 090408

Reference no: Pot FP Plus

Affected models

Following models are affected by this technical service bulletin:

FP 6000Q

FP 7000

FP 10000Q

FP 13000

Affected boards/modules

UI12Lx203, POT2B, UI12Lx403, POT4C.

Symptom

Distortion or dead channel due to bad potentiometers. Potentiometer VR10KLIN31HSBF replaces potentiometer VR10KLIN21H since the 21-step potentiometer has bad quality.

When doing service on a FP+ Series amplifier the potentiometers shall be exchanged if a POT-board with the old type of potentiometers is mounted. See picture below on how to identify the old type of potentiometer.

Solution

UI12Lx203 and POT2B needs to be changed to UI12Lx205 and POT2B04 to get the new potentiometers to fit.


UI12Lx403 and POT4C needs to be changed to UI12Lx405 and POT4C03 to get the new potentiometers to fit.

Note


Old potentiometers (see picture 1 below) have plastic axis (black) and the new potentiometer have a steel axis. Both POT-board and UI-board needs to be exchanged since the new POT-board does not fit with the old UI-board.

If the potentiometer VR10KLIN31_TOK (see picture 2 below) is mounted those does not need to be replaced, only potentiometers with plastic axis needs to be replaced. Difference between VR10KLIN31_TOK and VR10KLIN31HSBF is the supports on the sides.


Picture below shows difference between old and new potentiometers.




Picture 1: Old type of potentiometers.



Picture 2: The VR10KLIN31_TOK potentiometer.



Picture 3: The VR10KLIN31HSBF potentiometer.



Picture 4: The VR10KLIN31HSBF potentiometer, solder side.

Part numbers

Model	Part number to be ordered
FP 6000Q	VR10KLIN31HSBF, UI12Lx405, POT4C03, MH2x81ML, SUI12Lx4FP6KQ02, BUI, 2pcs SSDS5x72
FP 7000	VR10KLIN31HSBF, UI12Lx205, POT2B04, MH2x81ML, SUI12Lx2FP7K02, BUI, 2pcs SSDS5x72
FP 10000Q	VR10KLIN31HSBF, UI12Lx405, POT4C03, MH2x81ML, SUI12Lx4FP10KQ04, BUI, 2pcs SSDS5x72
FP 13000	VR10KLIN31HSBF, UI12Lx205, POT2B04, MH2x81ML, SUI12Lx2FP13K04, BUI, 2pcs SSDS5x72

History

Date	Created By	Status	Bulletin no.	Comment
080930	JF	DISCONTINUED	7	REPLACED BY BULLETIN NO. 13
090408	PB	SHARP	13	