TECHNICAL BULLETIN



MODEL/DERIVATIVE:

Range Rover
Discovery Series II
Freelander

Bulletin Nº: **0045** CDS. ref: **L8719bu**

Issue: 1

Date: 09.01.02

AFFECTED RANGE:

All vehicles

PROBLEM:

INTERMITTENT ELECTRICAL PROBLEMS

The engine may not start / starts intermittently.

CAUSE:

The battery clamp nut and bolt on the positive or negative terminal may break.

ACTION:

Where a complaint of the above is confirmed, follow the procedure below to replace the battery clamp nut and bolt, which is now available from Land Rover Parts.

Refer to PARTS INFORMATION for part number detail.

Procedure

- 1. Release fixings and remove battery cover, Range Rover and Discovery Series II only.
- 2. Remove broken nut and bolt from battery clamp.
- 3. Fit new nut and bolt to battery clamp and tighten to 5 Nm.
- Fit battery cover and secure with fixings, Range Rover and Discovery Series II only.

PARTS INFORMATION:

YTJ000010 - Nut and bolt

WARRANTY CLAIMS:

Use Complaint Code: 7E3D Use S.R.O.: 86.15.89/34

Range Rover / Discovery Series II

Time allowance: 0.10 Hrs

Freelander

Time allowance: 0.05 Hrs

Please do not return discarded parts to Land Rover.

TECHNICAL BULLETIN Nº: 0045 ISSUE: 1 PAGE: 1 OF 1