## **TECHNICAL INFORMATION**



No: 86/04/99/NAS

Ref: Issue: 1

Date: 03/19/99

### **Under-hood Ground Integrity**

AFFECTED VEHICLE RANGE:

DISCOVERY Series II (LT) ALL

#### SITUATION:

#### INCOMPLETE GROUND CIRCUITS CAUSING ELECTRICAL FAULTS

Loose or poor ground connections may cause electrical features to operate incorrectly.

#### RESOLUTION:

#### **INSPECT AND TORQUE UNDERHOOD GROUND POINTS**

When symptoms of a possible incomplete ground are present, follow the procedures detailed below to identify and correct the problem.

#### PARTS INFORMATION:

#### No parts involved

#### WARRANTY CLAIMS:

86.70.89/59 .....Time 0.30 hrs.

Inspect and torque under-hood ground locations.

**FAULT CODE:.K** 

Normal warranty policy and procedures apply


#### REPAIR PROCEDURE:

#### PROCEDURE TO OBTAIN A GOOD GROUND:

- 1. Remove the fastener that holds ground wires to the vehicle.
- 2. Inspect the post and nut or bolt for corrosion.
- 3. If the mating surfaces or the post and nut are corroded, use a wire brush to clean them.
- 4. If the surface where the eyelet contacts the vehicle is a painted surface, place a star washer between the painted surface and the eyelet.
- 5. Replace the eyelet and tighten the nut or bolt to 8 to 10 Nm (65 to 90 lbf.in.).
- 6. Coat complete connection with anti-corrosion wax.

## INDIVIDUAL UNDERHOOD GROUND POINT INSPECTIONS

- Inspect ground points C558. C559, C560, C810, and C811. (Figure 1)
- 2. Torque retaining nuts as outlined in "Procedure to Obtain Good Ground."




| TIB          | CIRCULATE: | Service Mgr | Warranty | Workshop | Body Shop | Parts |
|--------------|------------|-------------|----------|----------|-----------|-------|
| 86/04/99/NAS | TO         | X           | X        | X        | X         |       |

© Rover Group 1999 Page 1

# **TECHNICAL INFORMATION**



- 3. Inspect ground points C557, C709, C807. (Figure 2)
- 4. Torque the retaining nut as outlined in "Procedure to Obtain Good Ground."



- 5. Inspect braided wire ground point fastener from back of LH cylinder head to bulkhead. (Figure 3)
- 6. Hold wire terminal in position to prevent twisting.
- 7. Torque 13mm retaining bolt as outlined in "Procedure to Obtain Good Ground."

