

KENWOOD

ASB-1022

Service Bulletin

Amateur Radio Division

Subject: MC-44/MC-44DM Intermittent Modulation

Date: May 18, 1993

Symptom:


Microphone audio is mechanically intermittent., i.e. striking the microphone will cause audio to be lost or restored.

Cause:

The lead wire of capacitor C8 might be shorting out against the case of the ECM unit.

Corrective Action:

Re-install the capacitor so that the leads cannot touch the ECM case.



Make sure the leads of C8 100 pF capacitor do not touch the ECM case.