

ALLEN & HEATH



WARNING – HIGH VOLTAGES


Power Supply Unit (PSU) work should only be carried out by qualified personnel.

We recommend that you use an approved Allen & Heath service centre for all power supply work.

Please contact your local Allen & Heath distributor for more details.





<http://www.allen-heath.com/>

UNDERSIDE VIEW




REAR

BROWN
WHITE
YELLOW



☐ = CRIMP TERMINAL ● = SOLDERED TERMINAL

1. NEATLY FORM HARNESSES USING CABLE TIES.
2. CONNECTORS SHOWN SOLDERING VIEW.
3. WIRE IS 16/0.2 UNLESS SHOWN 7/0.2.
4. SLEEVE ALL CONNECTIONS WITH H15, H20 OR H30.



ROB

RPS3 WIRING

