

TECHNICAL BULLETIN



MODEL/DERIVATIVE:
Range Rover (LP)

Bulletin N°: **0042**
CDS. ref: **L8696bu**
Issue: **2**
Date: **27.02.02**

AFFECTED RANGE:
All vehicles up to VIN 2A 463528

RE - ISSUE INFORMATION:
PARTS INFORMATION amended.
Please destroy your existing copy and replace with this Issue 2.

PROBLEM:
HANDSET FAILS TO LOCK VEHICLE
The vehicle may not lock when the lock button is pressed.

CAUSE:
Handset fault.

ACTION:
Where a complaint of the above is confirmed, replace the handset with the new type, which is now available from Land Rover parts.
For synchronisation of the handset, refer to Workshop Manual, Electrical, Description and Operation, resynchronisation.

PARTS INFORMATION:
ASR1940 - UK - key one
ASR1941 - UK - key two
ASR1942 - Europe - key one
ASR1943 - Europe - key two
ASR1946 - ROW - key one
ASR1947 - ROW - key two
STC3634 - UK and Europe - key three
STC3635 - UK and Europe - key four

WARRANTY CLAIMS:

Use Complaint Code: 6S3D

Use S.R.O.: 86.77.33

Time allowance: 0.10 Hrs