

TECHNICAL BULLETIN



MODEL/DERIVATIVE:

Freelander

Bulletin N°: 0008
CDS. ref: L8675bu
Issue: 2
Date: 30.01.02

AFFECTED RANGE:

All vehicles

RE - ISSUE INFORMATION:

WARRANTY CLAIMS: Complaint Code amended.

Please destroy your existing copy and replace with this Issue 2.

PROBLEM:

FRONT PROPELLER SHAFT, SLIDING JOINT AND GAITER - RENEW

CAUSE:

Previously no procedure or parts were available to repair the front propeller shaft sliding joint and gaiter.

ACTION:

Repair procedure and parts are now available for the front propeller shaft, sliding joint and gaiter.

Whenever a propeller shaft, sliding joint and gaiter repair is to be carried out, refer to the Freelander Workshop Manual LRL0350 (2nd Edition), repair number 47.15.15 for repair procedure.

PARTS INFORMATION:

Description	Part Number	Contents
Propeller shaft front joint – repair kit	TVF000010	Grease sachet
		Circlip
		Tripode assembly
		Seal
		Back can
		Anti-balloon ring
		Gaiter
		Stabilising ring
Hose clip		

WARRANTY CLAIMS:

Use Complaint Code: 4K5E

Use S.R.O.: 47.15.15

Time allowance: 1.40 Hrs