

TECHNICAL BULLETIN



MODEL/DERIVATIVE:
Discovery Series II

Bulletin N°: **0079**
CDS. ref: **L8720bu**
Issue: **2**
Date: **31.10.01**

AFFECTED RANGE:

All Vehicles with Electric seats from 2001 MY introduction

RE - ISSUE INFORMATION:

Technical Bulletin cancelled.

Please destroy your existing copy and replace with this Issue 2.

PROBLEM:

FRONT SEAT LUMBAR SUPPORT - NOT OPERATING CORRECTLY

- Reduced effectiveness from the lumbar support.
- Pocket on the rear of the front seat deformed.

CAUSE:

The seat was modified to make the occupant sit further back, this gives the impression of increased front leg room. Unfortunately, as a result of the modification, the lumbar support bladder pushes in the wrong direction.

ACTION:

This Technical Bulletin has been cancelled until further notice, please destroy your existing copy and replace with this issue 2.

PARTS INFORMATION:

Not applicable

WARRANTY CLAIMS:

Not applicable