

# TECHNICAL BULLETIN



**MODEL/DERIVATIVE:**  
**Freelander (LN)**

**Bulletin N°:** 0049  
**CDS. ref:** L8740bu  
**Issue:** 1  
**Date:** 06.03.02

**AFFECTED RANGE:**  
**All derivatives fitted with a Philips 770 radio**

**PROBLEM:**  
**THE RADIO/CLOCK DISPLAY DIGITS FAIL TO DISPLAY FULLY**

**CAUSE:**  
**A component within the radio/clock display unit is overheating.**

**ACTION:**  
**Where a complaint of the above is confirmed, replace the radio/clock display unit with a new radio/clock display unit now available from Land Rover Parts. Refer to Workshop Manual, Part Number LRL0350 (3<sup>rd</sup> Edition), Instruments, Clock, repair number 88.15.07.**

**PARTS INFORMATION:**

Part Number	Description	Quantity
XQH100102	Radio/clock display unit	1

**WARRANTY CLAIMS:**  
**Use Complaint Code: 7V7D**

**Use S.R.O.: 88.15.07**  
**Time allowance: 0.10 Hrs**

**Please return discarded parts to Land Rover - UK market only.**