

# TECHNICAL BULLETIN



*MODEL/DERIVATIVE:*  
**Discovery Series II**

*Bulletin N°:* **0090**  
*CDS. ref:* **L8745bu**  
*Issue:* **1**  
*Date:* **16.01.02**

*AFFECTED RANGE:*  
**All vehicles**

*PROBLEM:*  
**SPARE WHEEL MOUNTING BRACKET STUDS BREAKING DURING TIGHTENING OPERATION**

*CAUSE:*  
**Excessive torque applied to fixings.**

*ACTION:*  
**On refitting the spare wheel to the tail door mounting bracket ensure that the torque applied to the fixing nuts does not exceed 30 Nm. Applying a torque in excess of 30 Nm may cause a mounting bracket stud to break, in this case the mounting bracket should be replaced.**

*PARTS INFORMATION:*  
**Not applicable**

*WARRANTY CLAIMS:*  
**Not applicable**