




## INDEX

Model / Type	Problem	Number	Issue
Range Rover	STEERING WHEEL OFFSET IN LOW SUSPENSION PROFILE	001	1
All Models	STEERING BALL JOINTS - PREMATURE WEAR		 1
Discovery	OIL LEAKAGE FROM POWER ASSISTED STEERING (PAS) PIPES	002	1
Freelander	STEERING SENSITIVITY	003	1
Freelander	ROAD WHEEL ALIGNMENT - SPECIFICATION	004	1
Discovery Series II	POWER ASSISTED STEERING FLUID - SPECIFICATION	005	3
Defender	POWER STEERING FLUID - CHANGE TO SPECIFICATION	006	1
Discovery - right hand drive only	NOISE WHEN TURNING STEERING WHEEL - PAS	007	1
All Models	WHEEL ALIGNMENT SETTING PROCEDURE - MISINTERPRETATION	008	1
Discovery Series II	REPLACEMENT KEY INOPERATIVE	009	1
Freelander	ROCKING MOVEMENT ON STEERING WHEEL	010	1
Freelander	KNOCKING NOISE WITHIN STEERING SYSTEM	011	1
Freelander	STEERING PULLS TO ONE SIDE - VARIOUS	012	1
Discovery Series II	PAS SYSTEM - CHARACTERISTICS AND WARRANTY REPLACEMENTS	013	1
Range Rover	STEERING WHEEL ALIGNMENT CHANGES WITH CHANGES IN RIDE HEIGHT	014	1
Defender	UNNECESSARY REPLACEMENT OF PAS FLUID RESERVOIR	015	1
Freelander petrol	FLUID LEAKAGE FROM PAS FLUID RESERVOIR	016	1