

# TECHNICAL BULLETIN



*MODEL/DERIVATIVE:*  
**Freelander**

*Bulletin N°:* **0075**  
*CDS. ref:* **L8687bu**  
*Issue:* **1**  
*Date:* **5-Sep-01**

*AFFECTED RANGE:*  
**All vehicles prior to VIN number 1A 330720**

*PROBLEM:*  
**TAIL DOOR LATCH FAILURE**  
The customer may not be able to open the tail door or complain of a seized / stiff door latch.

*CAUSE:*  
**Dust can enter the door latch causing the mechanism to seize.**

*ACTION:*  
**Where a customer complaint of the above is confirmed, replace the tail door latch with the new improved latch, part number FQR000010.**  
**Refer to Workshop Manual, Doors, repair number 76.37.16 for repair procedure.**

*PARTS INFORMATION:*  
**FQR000010 – Tail door latch**

*WARRANTY CLAIMS:*  
**Use Complaint Code: 8V1F**

**Use S.R.O.: 76.37.16**  
**Time allowance: 0.60 Hrs**