

TECHNICAL INFORMATION



Revised Labor Time for Front Propeller Shaft Replacement

No: 47/02/05/NAS
FGN 205-01
Ref:
Issue: 1
Date: 26 September 2005

AFFECTED VEHICLE RANGE:

Discovery Series II (LT) All

SITUATION:

REVIEW OF LABOR TIMES REVEALS TIMING ERROR

As part of continual reviews and quality checks an error has been discovered in the original warranty time calculations related to the front propeller shaft replacement process. Although the actual process has not changed, it has been found that the original process timing included an error in timing for the front propeller securing bolts. This time has now been validated and the times corrected.

RESOLUTION:

REVISED TIME FOR PROPELLER SHAFT REPAIRS



NOTE: Associated repairs that require the new workshop procedure will also change.

To remove/install the front propeller shaft, follow the procedure outlined on GTR and referenced in the Repair Procedure section of this bulletin.

PARTS INFORMATION:

From Microcat as indicated for the repair.

DDW WARRANTY CLAIMS:



NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to DDW to obtain the latest repair time.

This Technical Bulletin has been issued for information only, to inform Authorized Repairers of a change in the Labor Time allowance to renew the front propeller shaft. The old labor time for front propeller shaft replacement (47.15.02) was 0.60 hours. DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

Description	SRO	Time (Hours)	Condition Code	Causal Part
Replace front propeller shaft	47.15.02	0.40		

Normal warranty policy and procedures apply.


NOTE: The information in Technical Information bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers."

If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether the bulletin applies to a specific vehicle.

TIB	CIRCULATE:	Service Mgr	Warranty	Workshop	Body Shop	Parts
47/02/05/NAS	TO	X	X	X	X	X

REPAIR PROCEDURE

REPLACE FRONT PROPELLER SHAFT

 **NOTE:** GTR lookup sequence is as follows:
GTR Home > NAS > Service Information/ LT
Discovery Series II/2004 > Workshop Manuals >
Discovery Series II Workshop Manual 1999 MY on >
Bookmark "47 PROPELLER SHAFTS" > Link
"47.15.02 Propeller Shaft Front"

1. Refer to GTR Workshop Manual Section 47.15.02 and replace front propeller shaft. (Figure 1)

