

S E R V I C E N O T E

SUPERSEDES: None

3455A Digital Multimeter

Serial Numbers: 0000A00000 / 9999A99999

Fan Replacement Kit available for defective cooling fan

Duplicate Service Notes:

3437A-10

3455A-30

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

Part No.	Description
03455-89801	Replacement Fan Kit

Situation:

The part number 3160-0266 has been discontinued by the part manufacturer. Effective immediately for the 3455A (& 3437A) , a new kit, P/N 03455-89801, will be used in its place.

Continued

DATE: June 1996

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
INFORMATION ONLY		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
RM	0940	

Solution/Action:

If the fan, "B1", fails, replace with new replacement fan kit (P/N 03455-89801). Some modification is required (see Replacement Fan Installation Note included in the kit).

Kit Contents:

- Replacement Fan W/Lugs
- Mounting and Support Hardware
- Replacement Fan Installation Note