

- L1 Power
- K5 Dual indicator
- L2 Connect AC to AC/DC input
- K2 Connect 115V AC to AC/DC input
- L3 Disable Shorts lamps
- L14 Connect AC/DC supply input to .1V AC x'far selects
- D17 Connect -.1V filtered DC to B17, C17, L10
- C17 Shunt self Bias Resistor cap
- B17 Connect filter across self bias resistors
- L5
- L9
- L10
- J1
- E17
- K6 Connect DC filter to L2
- H16 Connect DC filt 5K Ω Res to Dual Test switch
- J16
- K16 Connect AC TV to Meter Shunts
- L16 Connect DC filt 5K Ω Res to Meter Shunt
- E17 Connect FIL1 to Line Test Sw - for Leakage test (H-K)
- K17 DC filter output connect to 5K Ω 4W resistor
- L6 Connect Meter "-" to Cathode thru 100K Ω