

Self Bias Resistor Shunts

D13	10 Ω
E13	20 Ω
F13	30 Ω
G13	39 Ω
H13	100 Ω
J13	200 Ω
K13	300 Ω
L13	390 Ω

Heater to Cathode Leakage Shunts

H17	1K Ω
G17	2.2K Ω
F17	6.8K Ω

Meter Shunts

L7	5 Ω
L8	10 Ω
K8	20 Ω
J8	39 Ω
H8	82 Ω
G8	160 Ω
F8	330 Ω
E8	620 Ω
D8	1.3K Ω
C8	2.4K Ω
B8	5.1K Ω
A8	10K Ω

L6 Connect 100K Ω between meter shunt and cathode