Harman Music Group — Engineering Change Notice

Date: 11-3-04 **Project #:** 512
Product: Dbx PA
Assy. Name: See Below
Assy. Number:
Revision: **To:** F

Project Engineer: Jon Duffin / Ray Larsen
ECN # 3120

Reason For Change:
Improved manufacturability

Instructions:
Board Assembly 05-1790
Board 80-1790: Change to revision F & change display adaptor board to use cable 38-0009
PCB Assemblies 12-1790, 13-1790 & 05-1790: Change to revision F0, & remove Cable 38-0001.

Mechanical assembly 04-1790 add cable 38-0009 and change revision to L

****** Delete ******		**Quantity**	
Item Description	**Item #**	**From**	**To**
Ribbon Cable 20 Cond 2.5 In (PCB Assembly 05-1790)	38-0001	1	0

****** Add ******		**Quantity**	
Item Description	**Item #**	**From**	**To**
Ribbon Cable Card Edge (04-1790 Mechanical Assembly) Issue Location 7210	38-0009	0	1

Reason for Change	**Reason:**
Continuous Improvement	☐ CI
Cost Reduction	☐ CR
Component Substitution	☐ CS
Marketing Change	☐ MC
Manufacturing Release	☐ MR
Omission or Error	☐ OE
Product Enhancement	☐ PE
Regulatory Requirement	☐ RR
Software Update	☐ SU
Specification Change	☐ SC
Other:	☐ OTH
See Attached Impact Sheet **CostΔ**	**$**

Effectivity / Priority	**Priority:**
After Depletion of Current	☐ ADC
Next Job Release (2nd or 4th Friday of Month)	☐ NJR
Rework Parts	
On Order	☐ ROO
In Stock	☐ RIS
In Process	☐ RIP
In Finished Goods	☐ RIF
Other: Explain	☐ OTH

Signatures	**Date**
Engineering Manager	11/5/04
Materials / Set Effectivity Below	12/8/04
Manufacturing Engineering	12/8/04
Project Engineer All Documents approved	12/8/04
Effectivity	12/8/04
BK **ECN Distribution**	12-8-04

ECN_H April 21, 1998
Dist: STD; Engineering Files, Materials, Manuf. Eng., Manufacturing, Stockroom, Sales/Customer Service, Technical Service, Product Development, Proj. Engineer

BK