M63A

Supersedes: M63

Y2K update information on Pascal support software running under the following
operating systems:

300 WS, 300SRM-UX, 300 UX, 300 SRM-UX, 700 SRM-UX and 700 UX.

This Service Note applies to support software provided with the following
products.

11760, 8560, 8561, 8562, 8563, 8564, 8565, 8590, 8591, 8592, 8593, 869
4, 8595, 8596, 83620, 83630, 83640, 83650, 83621, 83631, 83651,
83622, 83623, 83624, 83642, 8340, 8341, 8711, 8712, 8713, 8714, 8715, 8720,
8721, 8722, 8752, 8753, 83751, 83752, 83711, 83712, 83731, 83732
Spectrum Analyzers, Sources and Network

Analyzers.

Serial Numbers:
0000A00000 / 9999Z99999

To Be Performed By: HP-Qualified Personnel, or Customer

Situation:
The Pascal operating environment has a defect related to the year 2000.

Solution / Action:
For the following platforms: 300 WS, 300SRM-UX, 300 UX, 300 SRM-UX,
700 SRM-UX and 700 UX

Take the following action:
1. Reset system date to 1980 and continue using the system
OR
2. Purchase upgrade (ver 3.25) for your operating system from Insolutions,
URL: http://www.insolutions-inc.com
OR
3. If you desire to change to a PC based solution, contact HP's Channel
Partner Intercal for the availability of an appropriate solution.

Date:
December 1998

****
*   *
*   INFORMATION ONLY   *
*   ----------------   *
*   *
*   AUTHOR/ENTITY: Herb Upham Microwave Instruments Division___ *
* ADDITIONAL INFO: _____ *
*   *
****

Copyright Hewlett-Packard Company 1998