



Customer Service

A Harman International Company

3 Oak Park Bedford, MA 01730

Tel (781) 280-0300, Fax (781) 280-0499

email: csupport@lexicon.com

## M300/L SERVICE BULLETIN

---

**SUBJECT:** Create a VLSI Lexichip 2 for the M300/M300L only

**REFERENCE:** ECO971218-00

**DISTRIBUTION:** International Pro Product Distributor Service Centers, Customer Service, Repair

**CORRECTIVE ACTION:** The Lexichip 2 chips on the DSP board of the M300/M300L have been replaced with Lexichip 2A's.

Del: P/N 330-09350 IC,DIGITAL,LEXICHIP 2 U9 and U35

Add: P/N 330-12589 IC,DIGITAL,LEXICHIP 2A U9 and U35

When ordering Lexichips for repairs in the field use P/N 330-12589 IC,DIGITAL,LEXICHIP 2A.

Please contact LEXICON CUSTOMER SERVICE with any questions.

---

SBM300/L\_971218\_00

Decmber 31, 1997

1