



Handling MOS components
MOS components are extremely sensitive to static charges. Please observe therefore the following regulations:
1. Components sensitive to static charges are stored and shipped in protective package. On the packages you find the subsequent symbol.
2. Avoid any contact of connector pins with foam packages and foils made of styro-por or similar chargeable package material.
3. Don't touch the connector pins when your wrist is not grounded with a conducting wristlet.
4. Use a grounded conducting mat when working with sensitive components.
5. Never plug or unplug PCBs containing sensitive components when the machine is switched on.

Subject to change
Copyright by WILLI STUDER AG
Printed in Switzerland
Order No. 10.30.1030 (Ed. 1188)


POWER SUPPLY UNIT 1.726.235.00




MICROCOMPUTER BOARD 1.726.275.00



RDS UNIT 1.726.280.20 (optional)



ANTENNA
INPUT
75 OHM



J3

- 16 ATR
- 15 USS
- 14 ATL
- 13 STMOD
- 12 MPX
- 11 STEREO
- 10 OVD
- 9 FMDAT
- 8 OVA
- 7
- 6 STRTU
- 5 +15V
- 4 -15V
- 3 SDATA
- 2 +33V
- 1 SYEN

TO P3
SUPPLY
UNIT