

# TECHNICAL BULLETIN



**MODEL/DERIVATIVE:**  
**Discovery Series II**

**Bulletin N°:** 0044  
**CDS. ref:** L8709bu  
**Issue:** 1  
**Date:** 09.01.02

**AFFECTED RANGE:**  
**All derivatives in VIN range 2A 736340 to 2A 753563**

**PROBLEM:**  
**NO CIGAR LIGHTER**  
**The customer may require a cigar lighter.**

**CAUSE:**  
**The cigar lighter was omitted due to feature re-alignment.**

**ACTION:**  
**The customer can now purchase a cigar lighter from Land Rover Parts.**  
**NOTE: The cigar lighter detailed in PARTS INFORMATION can only be fitted to vehicles from VIN 2A 736340.**  
**1. Remove blanking plate from fascia.**  
**2. Fit cigar lighter, detailed in PARTS INFORMATION.**

**PARTS INFORMATION:**  
**YUJ000050PMA - Cigar lighter**

**WARRANTY CLAIMS:**  
**Not applicable**