


CIRCULATE TO:-	
SERVICE MGR.	X
RECEPTION	X
WORKSHOP	X
PARTS	X

TestBook Information



MODEL	SUBJECT	04/10/95
	TestBook Information Bulletin- Introduction	TB/001/95/EN
	AFFECTED VEHICLES	
	LP LH LJ LD	

DETAIL

Land Rover are pleased to announce the introduction of a regular 'TestBook Information ' bulletin to assist all aspects of the business to understand current TestBook issues and to regularly update users of latest developments.


The introduction of this bulletin is designed to focus in on current TestBook technical issues which will enable the user to fully understand the operational side of the equipment.

Should you have any features or concerns with TestBook operating levels within the workshop enviroment, that can be utilised by other technicians, please inform us so that consideration can be given to the possibility of a bulletin being issued on this subject that all will receive the benefit of. A new bulletin contents and divider page has been issued with this first publication and should be placed in the current Technical Information bulletin binder to compliment existing service information

ACTION REQUIRED
 Insert new contents, divider page and TestBook bulletins in your Technical Information binder. Ensure this information is cascaded to all workshop personnel.

PARTS INFORMATION

Not applicable



PROCEDURE

Technical enquiries that arise from the use of TesBook should be directed to:

TestBook Help Desk

Telephone 01865 746699
Facsimile 01865 746653

WARRANTY
Not applicable

COMP. CODE
Not applicable

SRO
Not applicable