


CIRCULATE TO:-	
SERVICE MGR.	X
RECEPTION	X
WORKSHOP	X
PARTS	X

TestBook Information




MODEL New Range Rover All Automatic Derivatives.		SUBJECT Automatic Gearbox Diagnostic Problem	05/10/95 TB 004/95/EN
		AFFECTED VEHICLES LP All LH LJ LD	

DETAIL
 We have received reports that a number of Dealers have experienced difficulty when diagnosing Automatic gear box faults. Disc DRF 0004 UK has unsupported codes, and may lead the technician down the wrong diagnostic path. To over come the immediate problem using Disc DRF 0003 will allow full diagnostics testing. Disc DRF 0005 will be available for all markets September 1995, and has full supporting codes. All markets should ensure they are using the latest Disc where available.

ACTION REQUIRED
For information only- If latest Disc DRF 0005 not available use DRF 0003 for fault finding Automatic gear box problems.
 Ensure RDS 3.01 is installed on TestBook

PARTS INFORMATION

 Use Either Disc
 DRF 0003
 DRF 0005



- PROCEDURE**
1. Connect TestBook up to the vehicle.
 2. From the welcome screen, remove Disc 0004
 3. Insert
 - a. Disc DRF 0003 or
 - b. Disc DRF 0005
 4. Select model Derivative.
 5. Select Diagnostics System
 6. Select Automatic gear box Continue through fault diagnosis.
 7. Rectify any faults identified by TestBook
 8. Retest
 9. No faults found continue
 - 10 Exit.

WARRANTY
Not applicable

COMP. CODE
Not applicable

SRO
Not applicable