


CIRCULATE TO:-	
SERVICE MGR.	X
RECEPTION	X
WORKSHOP	X
PARTS	X

TestBook Information



MODEL New Range Rover		SUBJECT New Range Rover TestBook Adaptor - DTC0027	08/08/96 TB010/96/EN
		AFFECTED VEHICLES LP LH LJ LD	


DETAIL
 New Range Rover J1962 TestBook adaptors number DTC0027A or DTC0027B are no longer being repaired or replaced under the repair scheme within your TestBook agreement.

A total of 4 cables have been issued to replace these adaptors:-

J1962 Blue (DTC0061A) replaces DTC0027 switch position A
 J1962 Black (DTC0063A) replaces DTC0027 switch position C
 J1962 Grey (DTC0064A) and (DTC0057A) adaptor replaces DTC0027 switch position B

ACTION REQUIRED
 Use part numbers DTC0057A, DTC0061A, DTC0063A and DTC0064A instead of TestBook adaptor DTC0027 on the new Range Rover.

PARTS INFORMATION
 Not Applicable



PROCEDURE
 Not applicable

WARRANTY
 Not applicable

SRO Not applicable	COMP. CODE Not applicable
------------------------------	-------------------------------------