BULLETIN NEWS

The following bulletins have recently been added to your viewer. If you would like a preview now, click the 'PREVIEW' icon.

TECHNICAL BULLETINS Issue date: 06.03.2002

FREELANDER HANDBRAKE CABLE ADJUSTMENT – CHANGE TO PROCEDURE



Wk 10 2002

DISCOVERY SERIES II

IT HAS BEEN FOUND THAT A LARGE NUMBER OF ACE PUMPS HAVE BEEN UNNECESSARILY CHANGED. ONCE TESTED, THE ACE PUMPS HAVE BEEN FOUND TO BE OPERATING WITHIN SPECIFICATION.

FREELANDER

THE RADIO/CLOCK DISPLAY DIGITS FAIL TO DISPLAY FULLY



PREVIEW

