

S E R V I C E N O T E

SUPERSEDES: None

3455A Digital Multimeter**Serial Numbers:** 0000A00000 / 9999A99999

03455-66513 AC CONV Board 03455-66515 AC RMS Board

Part Change for Capacitor, P/N 0160-3945**Situation:**

The part number 0160-3945 was discontinued many years ago by the part manufacturer. A lifetime purchase of the part was made; however, that quantity proved insufficient. Effective immediately, a new part, P/N 0160-3945, will be used in its place.

Solution/Action:

Please note the following part number changes in the 3455A Service Manual Replacement Parts List.

Assembly	Old P/N	New P/N	Description	Ref Design.
03455-66513	0160-3945	0160-7613	CAP-FXD 39PF	C26
03455-66515	0160-3945	0160-7613	CAP-FXD 39PF	C27

DATE: 11 November 1991

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
INFORMATION ONLY		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
CMC	0900	REFER TO PCO 09-28610