




HENRY 5K CLASSIC RF DECK - MARK II



OPERATING CONTROLS - 3K CLASSIC X Mark II and 5K CLASSIC

- | | |
|---|-------------------------------|
| 1. Plate Current Meter. | 13. Adjustable Feet. |
| 2. Multimeter. | 14. RF Output Connector. |
| 3. Multimeter and Relay Control Switches. | 15. Cathode Fuse. |
| 4. STANDBY Light. | 16. RF Input Connector. |
| 5. POWER Light. | 17. ALC Connector. |
| 6. BAND Switch. | 18. RELAY Connector. |
| 7. TUNE Control. | 19. ALC Adjust Potentiometer. |
| 8. LOAD Control. | 20. Ground Stud. |
| 9. SSB/CW Switch. | 21. Serial Number Tag. |
| 10. OFF/ON Power Switch-Circuit Breaker. | 22. Air Flow Filter. |
| 11. AC Fuse. | 23. AC Power Connector. |
| 12. AC Fuse. | |



3K&5K CLASSIC POWER SUPPLY-LOWER DECK

7/30/88

