



4. ADDED AS SECONDARY OPERATION.
 2. ALL CAPACITORS IN MICROFARADS, EXCEPT AS NOTED.
 1. ALL RESISTORS IN OHMS

NOTES: UNLESS OTHERWISE SPECIFIED.

CARVIN 12340 World Trade Drive San Diego, CA 92128 (858) 487-1600 FAX 487-6629	
BR120 <i>System Master</i>	
DRAWN BY: GEORGE DREYER	DATE: 26SEPT05
APPROVED:	DATE:
PCB NO: 30-42120	REV: B
ASSY. NO: 80-42120	REV: B
REVISED BY: GEORGE DREYER	DATE: 2ARL06

Changes from Assembly Rev (A).
 Proto corrections: -15V via grounded, R257 grounded, Locational errors D11 moved up; added R11.

SMT SCREEN HOLES
 #690 #689