



Customer Service

A Harman International Company

3 Oak Park Bedford, MA 01730

Tel (617) 280-0300, Fax (617) 280-0499

## M300 SERVICE BULLETIN

---

**SUBJECT:** Replacement encoder part for Front Panel

**REFERENCE:** ECO970418-02

**DISTRIBUTION:** International Pro Product Distributor Service Centers, Customer Service, Repair

**CORRECTIVE ACTION:**

Component change on the front panel due to the discontinued production of Alps encoder. A Noble encoder has been approved to take its place and will be used when this component is in need replacement.

Del: P/N ( 452-04233 ) SW,RTY,INC,ENCODER,50 POS

Add: P/N ( 452-09762 ) SW,RTY,ENCODER,36 POS,VERT MNT

**Note:** The Alps encoder will be available until the current supply runs out. At that point, the Noble encoder will be taking its place.

Please contact LEXICON CUSTOMER SERVICE with any questions.

---

SBM300\_970418\_02

September 11, 1997

1