



REVISIONS			
REV.	DESCRIPTION	DWR/CHKD	Q.C./AUTH

- NOTES
- PART NUMBER LISTING IS FOR REFERENCE ONLY AND DOES NOT SUPERSEDE THE BILL OF MATERIAL #022-14708.
 - PUT CD & LITERATURE IN BAG. REFER TO BOM FOR LIST AND SEQUENCE OF LATEST DOCUMENTATION PACKAGE. FOLD & TAPE BAG.
 - PUT UNIT (WITH LITERATURE BAG ON TOP) IN BAG, FOLD AND SEAL BAG SO ALL CREASES AND SECURING TAPE ARE ON THE BOTTOM OF THE UNIT.
 - PLACE FOAM INSERTS ON ENDS OF SEALED UNIT AS SHOWN.
 - FOLD UP END OF BOX WITH STRAIGHT RECTANGULAR FLAPS. TAPE WITH CLEAR TAPE.
 - SLIDE UNIT INTO BOX. FOLD DOUBLE SCORED FLAP INTO BOX AGAINST THE FOAM INSERT.
 - PLACE APPROPRIATE POWER CORD IN THE END CAVITY. SEE BOM FOR PART NUMBER.
 - FOLD IN SMALL SIDE FLAPS AND CLOSE END FLAP. TAPE WITH CLEAR TAPE.
 - PLACE ID LABEL ON END FLAP IN SPACE PROVIDED.

UNLESS OTHERWISE SPECIFIED DIMENSIONS ARE IN INCHES TOLERANCES ARE: FRACTIONS DECIMALS ANGLES .XX +/- .010 .XXX +/- .005		ACAD 2000 FILE NAME 14719-0		lexicon	
MATERIAL MPX200		APPROVALS DRAWN AN 12/3/00		TITLE ASSY DWG, SHIPMENT, MPX200	
NEXT ASSY USED ON		CHECKED WH 1/18/01		SIZE FSCM NO. DWG. NO. REV.	
APPLICATION DO NOT SCALE DRAWING		Q.C. CW 1/22/01		B 080-14719 0	
		ISSUED JLM 1/22/01		SCALE N/A SHEET 1 OF 1	

LEXICON, INC.