Toyota/Lexus

*Fits '00-later V6 & V8, late models, type 3 & type 4 valve bodies.

(1) 77741-02K

Lockup Relay Control Valve Kit

Helps cure:

- TCC apply/release complaints
- Inadequate lubrication
- Converter codes





Helps cure:

- TCC apply/release complaints
- Converter codes
- Inadequate lubrication

Note: Requires tool kit F-97741-TL20 & the VB-FIX reaming fixture.

(3) 19741-01K

TCC Control Plunger Valve Kit

Note: EPC throttle control units only. Will not work on cable-style throttle control units.

Helps cure:

- Converter apply/release complaints
- Converter slip codes
- Overheated fluid






Helps cure:

- Converter complaints
- Overheated transmission
- Bushing wear & lube failure

Note: Requires tool kit F-97741-TL18 & the VB-FIX reaming fixture.



1 Automatic Drive • P.O. Box 440 • Bellows Falls, VT 05101-0440 USA (800) 843-2600 • (802) 463-9722 • F: (802) 463-4059 • www.sonnax.com



(5) 97741-01K

Dual-Ratio Boost Valve Kit

Helps cure:

- Soft upshifts
- Delayed Reverse/Forward
- Burnt brakes/clutches

(6) 97741-10K .353" EPC boost valve spool **97741-06K** .426" EPC boost valve spool

Oversized Pressure Regulator Valve Kit





Helps cure:

- Poor shift quality
- Low/High line pressure
- Converter complaints

Note: Both kits require tool kit F-97741-TL6 & the VB-FIX reaming fixture.

(7) 97741-19K

O-Ringed End Plug Kit

Helps cure:

- Soft shifts
- Slips & flared shifts
- Poor line rise

Note: Includes seven end plugs in various sizes. Follow usage chart included in instructions to determine correct location and size of O-ringed end plug.



This Sonnax kit also is available. see www.sonnax.com for details.

Click on Sonnax part numbers to see more information.