

HP 8566A/B instrument BUS cable pinout

Sub 'D' 50 way solder side view

17 16 15 14 13 12 11 10 9 8 7 6 5 4 3 2 1
33 32 31 30 29 28 27 26 25 24 23 22 21 20 19 18
50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34

IEE 448 50 way solder side view

25 24 23 22 21 20 19 18 17 16 15 14 13 12 11 10 9 8 7 6 5 4 3 2 1
50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31 30 29 28 27 26

Wiring key

SUB 'D'	IEE 448
1	26
2	1
3	27
4	2
5	28
6	3
7	29
8	4
9	30
10	5
11	31
12	6
13	32
14	7
15	33
16	8
17	34
18	9
19	35
20	10
21	36
22	11
23	37
24	12
25	38
26	13
27	39
28	14
29	40
30	15
31	41
32	16
33	42
34	17
35	43
36	18
37	44
38	19
39	45
40	20
41	46
42	21
43	47
44	22
45	48
46	23
47	49
48	24
49	50
50	25