



TECHNICAL ALERT

June 27, 2001

TA01 3001

NAS US Only Cda Only

ATTENTION: Service Manager Service Advisor Technician

Incorrect Vacuum Cap Installed in Production

A limited number of vehicles have had an old specification vacuum cap installed on the inlet manifold during production. A batch of these older parts was inadvertently delivered to the production line. A revised TIB with the extended VIN range will be issued shortly, but vehicles in retailer inventory should be corrected before delivery.

Please inspect your inventory for affected vehicles. Use the VIN list on the following page to ensure that the vacuum cap is corrected to the new specification part (LKD000020) for vehicles in your inventory as outlined in TIB 30/02/00/NAS:

REPAIR PROCEDURE


INSPECT AND INSTALL NEW PLUG

1. Replace hard plastic vacuum cap with the new style cap (LKD000020).

WARRANTY CLAIMS:

30.25.89/26.....Time 0.20 hrs.
Inspect for incorrect cap
and install new cap

Figure 1



DLR	VIN	DLR	VIN	DLR	VIN	DLR	VIN
101	1A721732	140	1A719857	197	1A718426	232	1A718122
		140	1A720078	197	1A718676		
109	1A720296	140	1A720146	197	1A718692	234	1A719852
		140	1A720325	197	1A720738	234	1A720731
110	1A717936	140	1A721010	197	1A721135		
110	1A717988	140	1A721049			235	1A717982
110	1A718155	140	1A721062	199	1A720211	235	1A718675
110	1A719758	140	1A721090	199	1A720366		
110	1A719911			198	1A720392	237	1A717931
110	1A720067	143	1A718141			237	1A718063
110	1A720389	143	1A718226	200	1A720482	237	1A718364
110	1A720719	143	1A718515	200	1A720522	237	1A720066
		143	1A718546	200	1A720666	237	1A721324
114	1A720137	143	1A719620	199	1A721710		
114	1A720353	143	1A720693			249	1A717958
				201	1A717961		
116	1A718689	152	1A720017			250	1A717924
116	1A719256			203	1A717917	250	1A718129
116	1A720923	156	1A717920			250	1A718150
115	1A721308	156	1A718189	204	1A720753		
						251	1A718757
121	1A718139	157	1A720642	206	1A718001		
121	1A718433			206	1A718007	255	1A720451
121	1A718514						
121	1A718616	163	1A718597	209	1A720723	263	1A721564
121	1A718684						
121	1A718725	169	1A719814	211	1A720263	271	1A718324
121	1A720401	169	1A720651				
121	1A721016	169	1A721053	212	1A718262	272	1A718012
121	1A721598					272	1A718016
		177	1A719923	213	1A718145	272	1A718295
126	1A718673						
		180	1A718441	217	1A718752	273	1A718759
132	1A717893						
132	1A718048	185	1A718050	224	1A719087	285	1A717894
132	1A718302	185	1A718210			285	1A717911
132	1A718332			225	1A718118	285	1A718008
132	1A718613	188	1A718695	225	1A718430	285	1A718153
		188	1A718701	225	1A718458	285	1A718592
133	1A718207	188	1A720576	225	1A720063	285	1A721881
133	1A718356	188	1A720727				
133	1A718687			226	1A720613	503	1A720623
133	1A720400	189	1A718483				
				228	1A720140	526	1A720516
136	1A718446	190	1A718736	228	1A720301	526	1A720631
136	1A718523						
136	1A718633	191	1A720090	230	1A718201	529	1A720491
				229	1A719819		
139	1A718067	193	1A718608				
139	1A718082	193	1A719951	231	1A718241		
		193	1A720485	231	1A718323		
		193	1A720916	230	1A718370		
		193	1A720977				

